# **SCALARWORKS**®

S H O O T E R D R I V E N®

# LEAP/12 OWNER'S MANUAL




Questions?

EMAIL SUPPORT

#### DISASSEMBLY


01.

Remove shroud screws using a T15 Torx driver.




02.

Remove factory mount by unscrewing factory screws using a Phillips head screwdriver.




#### ASSEMBLY

Slide mount into place between shroud and optic body. Visually inspect to verify proper seating.




Progressively tighten new base screws while firmly pressing driver bit into T25 socket.



#### ASSEMBLY

03.

Align and fasten factory shroud screws using T15 torx driver carefully to avoid cross-threading.



10 INCH-LBS MAX

#### OPTIONAL

01.

Install accessory rail using included T25 screws.



25 INCH-LBS MAX

#### INSTALLATION

## UNLOAD & MAKE WEAPON SAFE

Open clamp no further than internal stops allow to prevent clamp from wedging itself open.




O2. Hook Leap mount onto rail from ClickDrive Side and rock onto rail.



#### INSTALLATION

### UNLOAD & MAKE WEAPON SAFE

Close clamp by turning ClickDrive wheel clockwise as tightly as you can (Do not use tools).



PRO TIP USE YOUR RIGHT HAND TO TIGHTEN AND LEFT HAND TO LOOSEN